## **Bahamas** Maritime Authority

# Marine Safety Investigation Report

into a crush incident onboard Dole Chile with the loss of one life on 19 March 2022



The Bahamas conducts marine safety or other investigations on ships flying the flag of the Commonwealth of the Bahamas in accordance with the obligations set forth in International Conventions to which The Bahamas is a Party. In accordance with the IMO Casualty Investigation Code, mandated by the International Convention for the Safety of Life at Sea (SOLAS) Regulation XI-1/6, investigations have the objective of preventing marine casualties and marine incidents in the future and do not seek to apportion blame or determine liability.

It should be noted that the Bahamas Merchant Shipping Act, Para 170 (2) requires officers of a ship involved in an accident to answer an Inspector's questions fully and truly. If the contents of a report were subsequently submitted as evidence in court proceedings relating to an accident this could offend the principle that a person cannot be required to give evidence against themselves. The Bahamas Maritime Authority makes this report available to any interested individuals, organizations, agencies or States on the strict understanding that it will not be used as evidence in any legal proceedings anywhere in the world. You must re-use it accurately and not in a misleading context. Any material used must contain the title of the source publication and where we have identified any third-party copyright material you will need to obtain permission from the copyright holders concerned.

Date of Issue: 07 November 2022 Bahamas Maritime Authority 120 Old Broad Street LONDON EC2N 1AR United Kingdom

## Contents

1.	Summary	1
2.	Factual Information	2
3.	Analysis	7
4.	Conclusions	10
5.	Actions taken	11
6.	Recommendations	12
7.	Glossary and Definitions	13
App	oendix	14



## 1. Summary

### What happened

On 19 March 2022, the Bahamas registered hatch coverless container vessel, Dole Chile, was alongside, discharging containers at Santa Marta, Columbia. At around 03:30, with discharge continuing in close proximity, a deck fitter began hot work in bay 34, repairing a stopper from the lashing bridge.

With the repair almost completed the fitter was kneeling on a container in the cargo area to gain better access to the work area when he was struck by the container spreader attached to the vessel's gantry crane. He did not survive his injuries.

### Why it happened

The deck fitter was working alone and unsupported. His location had been relayed to the person controlling the cargo operations but this information did not alter the cargo discharge plan.

The design of the vessel's gantry crane meant that the operator's view of the casualty location was obstructed. There was no hatchman present to mitigate this hazard.

The officer overseeing the work, expected the repair to be completed from inside the lashing bridge's rails but the task could not be completed in the manner imagined – the victim moved onto the adjacent container in order to complete the repair.

### What can we learn

Personnel involved in any potentially hazardous operation should be consulted to identify the hazards associated with completion of the task. If you don't understand the task, you cannot identify the hazards. If you haven't identified the hazards you cannot assess the risk or implement effective controls.

Risk assessments are ineffective if risk control measures are not implemented.

When conducting work in port, clear and effective communication between the ship and terminal is key.



## 2. Factual Information

## **Dole Chile**

Vessel Type	Hatch coverless container	Flag	E	Bahamas						
Owner	Ventura Trading Ltd.	Manag	er F	Reefership Marine Services, LLC						
Classification Society	Registro Italiano Navale (RINA)	Gross/I Tonnag	Net ge	31,779 / 19,452						
Built	Kiel, Germany, 1999	Propul	sion S	Single engine driving fixed propeller						
IMO No.	Callsign	Length overall		Breadth	Depth (moulded)					
9185281	C6QX4	206.9 m		32.24 m	20.8 m					
La	st BMA Inspection			Last PSC Inspe	ction					
Wilmington, 20	December 2021. No deficie	encies.	Wilmir	ngton, 11 February 202	2. No deficiencies.					





#### Dole Chile - Marine Safety Investigation Report

Rank/Role on board	Deck Fitter (victim)	Master	Chief Officer	Second Officer
Qualification	Welder Performance Qualification	Master (unlimited)	Chief Officer (unlimited)	OOW (unlimited)
Certification Authority	LR	UK	India	India
Nationality	Indian	Indian	Indian	Indian
Age	41	57	29	35
Time in rank	5 years	15 years	2 months	2 years
Time on board	2 months	3 weeks	2 months	3 weeks

## **Environmental Conditions**

Wind	Wind	Wave	Swell	Precipitation	Light
Direction	Force	Height	Height	/ Sky	Conditions
East	2 - 3	N/A	N/A	None/Clear	Artificial (night)

## **Voyage Details**

At the time of the casualty the vessel was alongside at Santa Marta, Colombia.

The vessel was engaged in round-trip voyages, of about two weeks in duration, beginning at Wilmington (Delaware), USA, then to Santa Marta, Colombia, Moin, Costa Rica, and Puerto Castilla, Honduras, before returning to Wilmington.



### Narrative

All times in this report are UTC -5.

At 01:24 on 19 March 2022, Dole Chile moored, port side to, alongside at Santa Marta, Columbia, in preparation for cargo operations. Approximately thirty minutes later, discharge of empty containers started, which involved using one of the ship's gantry cranes and two shore cranes.

Prior to arrival, the chief officer had identified an opportunity in the cargo stowage plan to facilitate repairs to several damaged container mountings (stoppers). Due to their design, exposure and nature of the trade, the stoppers were regularly damaged and repairs were routinely carried out. To conduct these repairs, along with any other repairs on deck, the vessel carried three deck fitters, reporting to the chief officer.

The repair work to the stoppers (and the pads they landed on) could only be completed when they could be operated to verify alignment i.e., with no container blocking their deployment. In a planning meeting and toolbox talk, conducted the evening before arrival, it was agreed with the deck fitters that they would position their equipment in advance prior to retreating for rest, and complete the repairs once woken when access was available.



Stopper being deployed





Container resting on stopper

For the call in Santa Marta, it was intended to replace damaged stoppers on the port side (aft) of bay 22 (rows 06, 08 and 10) and on the starboard side (aft) of bay 34 (row 09). The work was considered crucial as full stacks of laden containers were scheduled to be loaded in these locations during the port call - the stoppers would be required to keep weight loading on the tanktop within allowable limits.



General arrangement showing locations of repairs to stoppers



As there were a total of five stoppers to be replaced at bay 22, two fitters were assigned to work there, with one fitter working alone to replace the single stopper at bay 34. Repairs of this type had previously been carried out by all three of the fitters and it was not unusual for them to work alone with no direct oversight.

On arrival at Santa Marta, bay 34 was fully loaded with empty containers – the plan was to discharge all the containers from tiers 20 and 22, along with several entire stacks (see plan, below). The repair was to be conducted at location 340920<sup>1</sup> (marked red on the plan) and could only be completed in a fixed time period: after the deck level container(s) had been discharged and before work started on the lower tiers.

Shore		Port									Sta	rboard	
•													
	22	ES	ES	ES	ES	ES	ES	ES	ES	ES	ES	ES	
_	20	ES	ES	ES	ES	ES	ES	ES	ES	ES	ES	ES	
-	▲ 18	ES	ES	E	Е	ES	ES	ES	Е	Е	ES	ES	
	16	ES	ES	E	E	ES	ES	ES	E	E	ES	ES	
	14	ES	ES	E	E	ES	ES	ES	E	E	ES	ES	
Tiers	12	ES	ES	E	E	ES	ES	ES	E	E	ES	ES	
	10	ES	ES	E	E	ES	ES	ES	E	E	ES	ES	
	08	ES	ES	E	Е	ES	ES	ES	Е	Е	ES	ES	
	06	ES	ES	E	E	ES	ES	ES	E	E	ES	ES	
	04	ES	ES	E	E	ES	ES	ES	E	E	ES	ES	
	02				E	ES	ES	ES	E				
		10	08	06	04	02	00	01	03	05	07	09	
							Rows						

#### Bay 34 on arrival. Containers marked ES to be discharged, containers marked E to remain onboard. The continuous black line denotes "deck level" - the lashing bridge

At around 02:30, the chief officer informed the officer of the watch (second officer) of the stopper repair plan. Shortly afterwards, the second officer then relayed the information about the nature and location of the welding to the stevedore foreman.

At approximately 03:30 the ship's aft gantry crane started discharging containers from bay 34 and the fitter was woken by the chief officer and told the bay would soon be clear. Once tiers 20 & 22 were discharged, he started the repair. Discharge continued from the port side of bay 34 as well as at bays 10 and 22 with the use of shore cranes.

At approximately 04:30 the fitter was seen, lying face down and motionless, on top of the container in position 340918. Cargo operations were immediately stopped, the alarm raised and paramedics called. First responders found him unresponsive with a significant visible head wound. He was declared dead by a medical doctor at 04:45.

An autopsy confirmed the cause of death as head trauma, consistent with being struck by the gantry crane's container spreader.



<sup>&</sup>lt;sup>1</sup> Bay 34, row 09, tier 20. See glossary for definitions.

## Safety Management

The vessel's safety management system (SMS) comprised of a series of manuals, checklists, permits to work and risk assessments. Guidance on hot work was limited to the section covering works in dry dock but there was a hot work permit and associated checklist.

The SMS system also included an Accident/Incident Library containing lessons to be learned from accidents in the fleet. This included the following, relating to a serious injury that occurred in 2021 when a junior deck officer was struck by a container spreader.

- Details and description of Basic/Root cause: Loss of situational awareness leading to misjudging of ongoing cargo handling equipment movement causing the accident.
- Proposed measures/corrective action: Proper risk assessment and situation awareness while executing a task and keeping check on changes undergoing in the task area as the task progresses to ensure that task is completed safely.

The last external audit of the SMS was conducted on 25 February 2022 showed no non-conformities or observations. Internal audits conducted on 11 July 2021 and 30 July 2020 listed a number of minor observations (unrelated to the casualty) and no non-conformities.



## 3. Analysis

The purpose of the analysis is to determine the contributory causes and circumstances of the casualty as a basis for making recommendations to prevent similar casualties occurring in the future.

### The accident

Scene examination and recreation suggests that the victim was hit by the outboard edge of the container spreader's girder as it was lowered when the victim was kneeling on top of container 340918 and facing aft. The presence of a slag removal hammer and the location of his welding equipment suggests he was inspecting his work or removing slag from welds.



Position of victim, as discovered by first responders (looking forward)

The location of the casualty was illuminated by floodlights on the bridge and accommodation block, facing forward, and on the gantry crossbeam, facing aft.

There were also lights fitted at the mid-point of the gantry boom. However, the victim may have not noticed the change of lighting as the gantry crane moved into position as he was wearing a welding mask (raised) and was facing the brighter lights aft.

### Visibility from gantry crane

The vessel was equipped with two gantry cranes. Each consisted of a central carrying crossbeam on two supports with a travelling trolley lifting system (boom and container spreader). At the time of the casualty, the aft crane was being used to discharge Bay 34. This crane was arranged with the driver's cab facing aft and offset to port (of the boom and spreader).





Views of aft gantry crane showing offset cab (looking from starboard)

The offset meant that the crane operator's view of the two rows to starboard of the cab was obscured. At the time of the casualty, the vessel was port side alongside, and the location where the victim was working would have been obscured when the spreader passed an area from Row 05 outboard as the gantry approached Row 09.



View from cab approaching, and at, location of casualty

The location in which the victim was working was not visible from the main deck.

Cargo operations were overseen by a stevedore foreman with hatchmen (spotters) assigned to each bay being worked, usually present on either a lashing bridge or the main deck. These personnel were in communication with each other and the gantry crane operators by radio. There was no direct line of communication between the hatchmen/crane operator and vessel's crew.

At the time of the casualty there was no hatchman at bay 34. The gantry crane operator stated that he saw sparks at the after end of bay 34 and knew that work was being done but, after seeing no sparks for a period of time, assumed that the work had finished.



### **Risk Controls**

Risk control for the repairs consisted of two elements: a toolbox talk held the evening before arrival and a task specific risk assessment. The toolbox talk, held on the bridge during the chief officer's watch, included discussing the work to be completed, pre-arrival positioning of welding equipment, establishing when personnel would be called and the contents of a task-specific risk assessment that had previously been drafted for similar work.

The task specific risk assessment "HOT WORK – Crop / renewal of stopper bar base plate / bracket in lashing bridge" had been completed on 13 March 2022 (see Appendix). Hazards identified were those associated with hot work – fire hazards in particular- and the need to control risk for falling was also included. There were no hazards identified relating to working cargo.

	Enter data in shaded cells - se	elect Likelihood & Severity from d	rop down o	ptions.				After a	pplying Co	ontrols
#	Identified Hazard associated with task	Possible consequences of the hazard	Likeli- hood	Severity	Risk Level	Existing Controls and Safeguards	Additional controls/safeguards required (Action Plan)	Likeli- hood	Severity	Risk Level
1	Defective cutting equipments like nozzles, flash back arrester	Injury & Damage to property	Moderate	Moderate	3	Regular inspection & maintenance to be carried out.	Checked prior use .	Low	Low	1
2	Defective welding cable	Injury	Moderate	High	4	Proper care & inspection of the cable to carried out frequently	Worn out/ chaffed cables to be discarded or diused immediately.	Low	Low	1
3	Improper use of PPE	Injury	Moderate	Moderate	3	Proper & appropriate PPE to be used at all times	Crew member should know the importance of PPE & should be trained in it's use	Moderate	Low	2
4	Fire Hazards	Injury & Damage to property	Moderate	High	4	All fire prevention measures to be taken, a fire watch should be posted until the completion of hot work	The company policy to be strictly followed & the work permit/ checklist duly filled & complied with.	Low	Low	1
5	Fire in adjacent spaces by conduction ot Radiation	Injury & Damage to property	Moderate	High	4	Thorough inspection of the adjacent spaces to be carried out prior and during hot work for any fire hazards	Elminate or reduce the the risk of ignition by taking appropriate fire prevention measure	Low	Low	1
6	Wet surface/ structure	Injury	Moderate	High	4	No hot work to be carried out on wet surface/ structure where there is a possibility of electricution	Faulty welding cables should not be used. Proper PPE to be worn during hot work	Low	Low	1
7	Slip trips and fall	injury or Death	Low	Moderate	2	Work place adequately lit up and safety barriers put.	Personnel working donned safety harnesses with fall preventers secured to a strong point.	Low	Low	1

Notwithstanding the unassessed risk posed by ongoing cargo operations, the risk assessment identified the following control measures:

- completion of hot work permit
- posting a fire watch
- ensuring adequate lighting and erecting safety barriers
- use of fall protection equipment

None of these control measures were in place at the time of the casualty, the fall protection equipment was not mobilised as the work was imagined to be completed from the lashing bridge (meaning the victim was exposed to a 5m fall to the deck when working on 340918). A hot work permit would have required a responsible person in attendance in addition to personnel carrying out the work. This was not done: the victim was working alone and unsupported.

The chief officer considered that the repair could be completed from the relative safety of the lashing bridge. However, to deploy and position the stopper, whoever was completing the task would, at minimum, have to extend their torso through the rails. They would then be left with incredibly limited mobility to complete the weld. Work as imagined did not correspond with work as done.

The chief officer believed that relaying the position of the ongoing hot work to the stevedore foreman was sufficient to control any risk posed by the ongoing cargo operation at Bays 22 and 34. No-one else, onboard or ashore, flagged that more needed to be done to complete the work safely.

## 4. Conclusions

- A deck fitter died after being struck by a moving container spreader whilst working in the cargo space next to the lashing bridge of bay 34.
- In the lead up to the casualty, the victim was working alone, unsupported and in close proximity to ongoing cargo operations.
- His location had been relayed to the person controlling cargo operations but the information did not alter the execution of the cargo plan. The information was not effectively passed to the gantry crane operator.
- The design of the vessel's gantry crane meant that the operator's view of the casualty location was obstructed. There was no hatchman present to mitigate this risk.
- The officer in charge of the work considered that the repair could be completed from the relative safety of the lashing bridge. However, work as imagined did not correspond with the risk this still posed or the restrictions it placed on completing the work.
- The task specific risk assessment for the work did not identify any hazards associated with working in proximity to ongoing cargo operations. The risk control measures that were identified including supervision, a fire watch, maintaining a boundary and protection from falls, were not implemented.
- Lessons from an earlier casualty, where a crewmember was seriously injured as a result of being struck with a container spreader, had not been effectively applied to the safety management system.



## 5. Actions taken

Reefership Marine Services LLC has:

- Sent members of the management team to each vessel in the fleet to share the details of this casualty
- Updated their risk assessments to include hazards posed by cargo operations
- Re-initiated a risk assessment training program that was on hold during the SARS Cov2 pandemic.



## 6. Recommendations

Reefership Marine Services is recommended to:

- Take action to improve the safety culture onboard Dole Chile and its other managed vessels, including but not limited to:
- Review the effectiveness of its safety management system's procedures and guidelines
- Review compliance with safe working practices, to better ensure the safety of its crews

Sociedad Portuaria de Santa Marta is recommended to:

- Ensure that effective oversight is provided at all hatches when cargo is being worked.
- Establish effective communication procedures between ship and terminal to facilitate repairs or maintenance of vessels moored at their berths. This should include agreement on the precautions to complete the work safely.



## 7. Glossary and Definitions

AB	Able seafarer
ASI	Annual Safety Inspection
Вау	Longitudinal division of container stowage. Bay number indicates the stowage
	position along the vessel's length. Numbers run from forward to aft.
BMA	The Bahamas Maritime Authority
Company	The Owner of the ship or any other organization or person such as the Manager, or the Bareboat Charterer, who has assumed the responsibility for operation of the ship from the Owner of the ship and who on assuming such responsibility has agreed to take over all the duties and responsibilities imposed by the International Safety Management (ISM) Code
m	Metre. Unit of length. 1m equals 1000mm
No.	Number
PSC	Port State Control
Row	Transverse division of container stowage (stacks). Numbers run from midships increasing outward – odd numbers to starboard, even number to port.
SMS	Safety Management System
Terminal	The operator of the port facility responsible for the loading and discharge of cargo to/from ships and any ancillary operations
Tier	Horizontal division of container stowage. Numbers increase from hold bottom to deck.
USCG	United States Coast Guard
UTC	Universal Time Coordinated



## Appendix

## **Risk Assessment**

and a constrained of the constra	58	RISK ASSESS	MENT & REVIEW	FORM				Task has existing checklis Use the quide on page 2 for t	st , Y/N: the Risk	Assessm	l
Monthly Control memory length         Monthly Control memory length         Monthly Control memory length           Monthly Control memory length         Monthly Control memory length         Monthly Control memory length           Monthly Control memory length         Monthly Control memory length         Monthly Control memory length           Monthly Control memory length         Monthl	esse	: MV DOLE CHILE				Date:	13-Mar-22	Complete "Reviewed by" sec	ction on	page 2 bo	ottom
Test Supervise:       Test Supervise       Test Supervise:		Project / Task Identification:	HOT WORK - Crop / renewal of sto	opper bar ba	ise plate / b	racket in	lashing bridge	DK :012/22			
Electron of a consolution of a consolutio of a consolution of a consolution of a consoluti		Task Supervisor.	CHIEF OFFICER				Department Head/Assessor:	CHIEF OFFICER			
Image: Control control control     Control conteconte contro		Enter data in shaded cells - se	elect Likelihood & Severity from dr	lo umop do	otions.				After a	pplying Co	ontrols
1     Genetic entrine entrine fragmention     Marcial fragmention     Marcial fragmention     Low	#	Identified Hazard associated with task	Possible consequences of the hazard	Likeli- hood	Severity	Risk Level	Existing Controls and Safeguards	Additional controls/safeguards required (Action Plan)	Likeli- hood	Severity	Risk Level
2     Jenetone wetling cale     Juny     Juny <td< td=""><td>-</td><td>Defective cutting equipments like nozzles, flash back arrester</td><td>Injury &amp; Damage to property</td><td>Moderate</td><td>Moderate</td><td>3</td><td>Regular inspection &amp; maintenance to be carried out.</td><td>Checked prior use .</td><td>Low</td><td>Low</td><td>۲</td></td<>	-	Defective cutting equipments like nozzles, flash back arrester	Injury & Damage to property	Moderate	Moderate	3	Regular inspection & maintenance to be carried out.	Checked prior use .	Low	Low	۲
3       Information of PEE	N	Defective welding cable	Injury	Moderate	High	1.4	Proper care & inspection of the cable to carried out frequently	Worn out/ chaffed cables to be discarded or diused immediately.	Low	Low	-
4       File friedradie       Injur & Damage to property       Modenie       High       An Interprevention material calculation in the most primerical in the most primerical calculation calculation in the most primerical calculation calculation in the most primerical calculation calculatin calculation calculation ca	б	Improper use of PPE	Injury	Moderate	Moderate	9	Proper & appropriate PPE to be used at all times	Crew member should know the importance of PPE & should be trained in it's use	Moderate	Low	7
5       For the adjacent species by conclusion of chandian       Injury & Damage to property (and injury and and injury properties of chandian       Injury & Damage to property (and injury and and play or Dearth       Injury & Damage to property (and injury and and play or Dearth       Injury & Damage to property (and injury and and play or Dearth       Injury & Damage to property (and injury and and play or Dearth       Injury & Damage to property (and injury and and play or Dearth       Injury & Damage to property (and injury and and play or Dearth       Injury or Dearth	4	Fire Hazards	Injury & Damage to property	Moderate	High	4	All fire prevention measures to be taken, a fire watch should be posted until the completion of hot work	The company policy to be strictly followed & the work permit checklist duly filled & complied with.	Low	Low	-
6       Meteratory structure       Injury or beam       High       High       And work to be carried out on two structures structures structures and and provork.       Low       Low <thlow< th=""> <thlow< th=""> <thlow< th="">       Low</thlow<></thlow<></thlow<>	5	Fire in adjacent spaces by conduction ot Radiation	Injury & Damage to property	Moderate	High	4	Thorough inspection of the adjacent spaces to be carried out prior and during hot work for any fire hazards	Elminate or reduce the the risk of ignition by taking appropriate fire prevention measure	Low	Low	-
7       Sip types and fall       upuy or Death       Low       Low       Moderate       2       Work place adoquately if up and safety       Low       <	ω	Wet surface/ structure	lnjury	Moderate	High	4	No hot work to be carried out on wet surface/ structure where there is a possibility of electricution	Faulty welding cables should not be used. Proper PPE to be worn during hot work	Low	Low	-
8         9         1	7	Slip trips and fall	injury or Death	Low	Moderate	2	Work place adequately lit up and safety barriers put.	Personnel working donned safety harnesses with fall preventers secured to a strong point.	Low	Low	-
9     10 <t< td=""><td>œ</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>	œ										
10     10     11     12     Average Risk     1     1     1     1     1       12     12     Average Risk     3.4     Average Risk     1.1       Average Risk     3.4       Average Risk     3.4       Average Risk     1.1       Cleaverage Risk     1.1       Average Risk	6										
11     11     12     12     Average Risk     3.4     Average Risk     1.1       12     12     Average Risk     3.4     Average Risk     1.1       Crew briefed about the procedures to be followed and PPE to be worn at all times.       Fage       Crew briefed about the procedures to be followed and PPE to be worn at all times.	10										
12     12     Average Risk     3.4       Average Risk     3.4       Summary of Action Plan:       Crew briefed about the procedures to be followed and PPE to be worn at all times.       Fage       If risks assessment dictates a change or deferment of the task, summarize the reasons above.       Page: 1/2       Original: 10/10     Subject: Checklist/Standing Inst.       Date: July, 20     Prepared by: KC       Page: 1/2     Chapter: Risk Assessment & Review Form	Ŧ										
Summary of Action Plan:     Average Risk     3.4     Average Risk     1.1       Crew briefed about the procedures to be followed and PPE to be worn at all times.     Average Risk     3.4     Average Risk     1.1       If risks assessment dictates a change or deferment of the task, summarize the reasons above.     Date: July, 20     Prepared by: KC     Page-1       Page: 1/2     Chapter: Risk Assessment & Review Form     Date: July, 20     Prepared by: KC     Page-1	12										
Crew briefed about the procedures to be followed and PPE to be worn at all times. If risks assessment dictates a change or deferment of the task, summarize the reasons above. Page-1 Original: 10/10 Subject: Checklist/Standing Inst. Date: July, 20 Prepared by: KC Page-1 Page: 1/2 Page:	Sumr	nary of Action Plan:		Ave	age Risk	3.4			Ave	rage Risk	1.1
If risks assessment dictates a change or deferment of the task, summarize the reasons above. Page-1 Original: 10/10 Subject: Checklist/Standing Inst. Date: July, 20 Revision: 1/20 Chapter: Risk Assessment & Review Form Page: 1/2 Page: 1/2	Crew	briefed about the procedures to b	e followed and PPE to be worn at all t	imes.							
Original: 10/10         Subject: Checklist/Standing Inst.         Date: July, 20         Prepared by: KC           Revision: 1/20         Chapter: Risk Assessment & Review Form         Approved by: MC	If risk	s assessment dictates a change o	r deferment of the task, summarize th	le reasons a	sbove.						Page-1
		Original: 10/1 Revision: 1/2/ Page: 1/2	0 Subject: Checkl 0 Chapter: Risk A	ist/Standing ssessment	g Inst. & Review	I / Form	Date: July, 20	Prepared by: KC Approved by: MC			



								1	Page-2	7
Dole Keejersnip Marine Services	Potential Controls (Rei QSMS 7.11.14) - Controls must be put in place wherever possible to reduce risks to the minimum. e.g. Safety controls Anti-pollution Controls, SOPEP deployment Enhanced procedure – afloat Clear defined responsibilities Enhanced procedure – ashore Reporting requirements, commuication Inspection prior commiting Reallocating skilled staff Familiarisation process Enhanced training programme Use of technology, additional equipment Monitoring for deviations, elect isolation, etc PMS status checks	For Control Actions to reduce the risk rating use the ALARP (as low as is reasonably practicable) principle.	Overall Risk Rating	Acceptable Tolerable Control action required to reduce to acceptable/tolerable Control action required to reduce to acceptable/tolerable	Unacceptable - Control action required	Lrew signatures redacted	Implement Monitor / Review Re-Assess		Task supervisor.	Prepared by: KC Approved by: MC
RISK ASSESSMENT — GUIDE	Potential hazards & consequences (Ref QSMS 7.11.9) - Review must consider all risks & possible consequences. - Hazards can vary from the obvious to those listed below e.g of hazards Fire, explosion, furnes, smoke, toxic gas, low oxygen Electrical shock, mechanical failure. Silpping, tripping, low head room, falling objects or tools Safety equipment or PPE failure Safety equipment or PPE failure Structural weakness, poor tools Structural weakness, poor tools Firesence of oil or other pullutants, hazmats e.g. of severity and consequences Threat to life & limb Damage to environment - short or long term Damage to company reputation, business Loss of voyage, financial or commercial loss	OR NO RISKS ASSESSED	por	Very Low         1           Low         2           Nedium         3           Datt         High	bod #		Consequences Controls DECISION	Crew signatures redacted	Chief Engineer: or Chief Officer:	tanding Inst. Date: July, 20 sment & Review Form
	is I team		od High Likelihr High Impa	od High Likelih Moderate Im	od High Likelih Low Impar	×	Intification sess/What IP?		Dept. Head:	Subject: Checklist/S Chapter: Risk Asses
marcicina	ief Engineer, Task su area of knowledge he he circumstances. embers of RMS/DFF embers of RMS/DFF		4 Moderate Likeliho High Impact	3 Moderate Likeliho Moderate Impaci	2 Moderate Likelihov Low Impact	Likelihood of Risi Occuring	Hazard Ide Analyse/As			0.0
magnun wante	Include: artments, Master, Chi a appropriate whose a ed as appropriate to t other appropriate mu ons rechnical sk/Marine/Safety ting sing sing becurity Outside consultants		3 Low Likelihood Hiah Impact	2 Low Likelihood Moderate Impact	1 Low Likelihood Low Impact	Î	Project or Task to be Undertaken		<del>]</del> :	Original: 10/1 Revision: 1/2 Page: 2/2
e pup fuin	Reviewers to leave Head of Depe Other staff as been identifie If considered, e.g. Operatic Account Purchas Crewing CSO - S CSO - S Cothers,		Impact of Dick						Master.	

Bahamas Maritime Authority