

Make and Type Listing:

Equipment	Type, Series or Range	Manufacture	
Survival crafts	JY-FN, JY-FF, JYM-FN, JYM-FF, GJ, JY-QFP/N		
Launching appliances	JYL, JYF, JYP, JYR, JYRC, JYRH	JIANGSU JIAOYAN (JIANGYIN XINJIANG)	
Winch	JYW, JYWP		
Release gear	JX, JXN		
Survival crafts	BH, BH-F, BH-R, BH-HR	QINGDAO BEIHAI	
Launching appliances	BD-PV, BD-FF, BD-SA, BD-SH,		
Winch	BW-H(L/R), L(L/R), SC, YSB		
Release gear	BG, BH-HOOK, FS, 15KN, 25KN, 35KN		
Survival crafts	HH, GJ	WUXI HAIHONG	
Release gear	НН		
aunching appliances	HML, HMD,	WUXI HUAHAI	
Winch	HMW		
Survival crafts	WJB, WJ, BJ	WUXI WHENJIAO	
Release Gear	WJHK, WJ		
Survival Crafts	YH	ZHENJIANG MARINE AUXILIARY MACHINERY	
aunching Appliances	LE, HE, RE, SRH, GL, TG, HT, LC, FH, SAF, SAFC, SA, HDCL, LA, PL, LFR, LFRH, LEFR, DH, SAW, SAWH		
Release gear	HK, SH		

 The equipment listed above should be understood as: Survival craft: any lifeboat type including but not limited to freefall lifeboat, totally or partially enclosed LB, fitted with or without sprinkler/deluge system, fitted with or without an air cylinder, tender boat, rescue boat, inboard or outboard engines, propeller, or jet drives. Launching appliances: any davit type system including but not limited to davit launched life-raft, secondary means of deployment and rescue boat davit. Release gear: any hook release gear such as but not limited to onload/offload, freefall hydraulic, rescue and fast rescue boat release gear. Winch: any which types including but not limited to single/twin drum, hydraulic and electric.

3. When a sub-contractor is acting as an independent company on behalf of a BASP, the attending sub-contractor is to be listed and included in the original BASP certificate of Authorisation.

Some equipment might be not clearly identified as unique equipment type/range and might be part of the same skid unit assembly or rebranded under a new parent company name. In such cases when evidence is provided to the attending RO's surveyor, this can be automatically be accepted by the attending surveyor without consulting the BMA.