#### **INFORMATION NOTICE 28**

# **Bahamas**

Version No. 1.1

Issue Date 15/08/2022

Effective Date 15/08/2022

# Shipboard preparedness for emergency steering in Port Hedland

Notice to ship owners, managers, Masters, Approved Nautical Inspectors, Recognised Organisations and surveyors

#### **Purpose**

1.1. This Notice provides awareness of shipboard preparedness for emergency steering requirements to comply with the Pilbara Ports Authority Notice 05/22 for ships calling to Port Hedland.

## 2. Application

2.1. This Notice applies to all vessels calling to Port Hedland.

#### 3. Introduction

3.1. Based on recent events at the Port of Port Hedland, effective 17 June 2022, all vessels calling at Port Hedland are required to have a suitably qualified and competent person on standby in the vessel's steering gear room when the vessel is navigating in port waters.

### 4. **Port Requirement**

- 4.1. For inbound vessels: The standby person must be present in the steering gear room from the time the vessel enters the Port Hedland shipping channel, until the vessel is alongside the berth.
- 4.2. For outbound vessels: The standby person must be present in the steering gear room from the time all mooring lines are released, until the vessel has passed beacons 15/16 in the shipping channel.
- 4.2.1. The standby person in the steering gear room should be:
  - i. Trained in carrying out emergency steering and should be provided with a direct means of communication to the vessel's bridge.
  - ii. Able to identity and communicate the actual position of the rudder to the bridge (rudder angle) when requested.

#### SHIPBOARD PREPAREDNESS FOR EMERGENCY STEERING IN PORT HEDLAND



- iii. Able to change over to local emergency steering mode and steer the vessel as per directions from the vessel's bridge.
- iv. Only dismissed from steering gear room in consultation with the pilot.
- 4.3. The vessel's Master must ensure that the standby person in the steering gear room does not operate any machinery unless instructed by the bridge.





Actual Position of the Rudder





Actual Position of the Rudder

## 5. Sources and references

5.1. <u>https://www.pilbaraports.com.au/PilbaraPortsAuthority/media/Documents/Port%20of</u> <u>%20Port%20Hedland/Safety%20and%20Security/Local%20marine%20notices/2022/PH-</u> <u>05-22-(P)-Preparedness-for-Emergency-Steering-in-Port-Waters.pdf</u>

SHIPBOARD PREPAREDNESS FOR EMERGENCY STEERING IN PORT HEDLAND



# **Revision History**

	listory	
Version	Description of Revision	
1.0	First Issue	
1.1	Editorial amendments	
		7
		T
		X
		7
	CD FCC	